

ERRATA 2

NOTES:

1. NO HORIZONTAL OR VERTICAL BENDS ARE ALLOWED IN THE FIRE HYDRANT BRANCH.
2. PROVIDE A 48-INCH DIAMETER SONOTUBE AROUND CIRCUMFERENCE OF FIRE HYDRANT.
3. COORDINATE CONSTRUCTION ACTIVITIES WITH DENVER INTERNATIONAL AIRPORT AND DENVER WATER CONSTRUCTION INSPECTION.

DENVER WATER

DENVER INTERNATIONAL AIRPORT AIRSIDE FIRE HYDRANT ASSEMBLY

Scale: NONE	Date: January 2020
Drawn: RLB	Ck: K ROSS
Approved:	Dr. 127 No. 35